

Macintosh LC III Power Supply (USA version by ASTEC)

Should be replaced:

Two: 120uf @ 10V
Two: 2200uf @ 10V
One: 1200uf @ 16V
One: 1000uf @ 10V
One: 470uf @ 16V

Should not need replacing: One: 180uf one: 180uf @ 400V One: 47uf @ 25V

For a full capacitor parts list and details visit: www.Mac84.net/guides

